



View looking west from W Winton Ave near Hesperian Blvd

ATTACHMENT III



View looking east from W Winton Ave at Clawiter Road



ATTACHMENT III







West of Hesperian Blvd along Airport property fence









ATTACHMENT III



ATTACHMENT III





Photo 1

Photo 2



Photo 3

Photo 4



ATTACHMENT III
























Trees in poor condition at the western the Golf Course property fence along the railroad right-of-way directly over the pipeline